## oK

## WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

October 7, 2004

TO:	Internal File	i			
THRU:	D. Wayne Hedberg, Permit Supervisor	1			
FROM:					
RE:	2004 Second Quarter Water Monitoring, Canyo Loadout, C/007/0034-WQ04-2, Task ID # 2007	on Fuel Company	, Banning Siding		
	data submitted for all of the MRP required sites?  Identify sites not monitored and reason why, if known:	YES 🖂	NO 🗌		
	The Truck Dump Sump is the only MRP required mon only one sample per year is required, in the "late fall" a				
2. On what date does the MRP require a five-year resampling of baseline water data. See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.					
Resam	pling due date				
	There is no commitment in the MRP to resample for ba	seline parameter	S.		
	re all required parameters reported for each site?  Comments, including identity of monitoring site:	YES 🖂	№ □		
	re irregularities found in the data?  Comments, including identity of monitoring site:	YES	NO 🛚		

Page 2 C/007/0034-WQ04-2 Task ID #2007 October 7, 2004

5.	5. Were DMR forms submitted for all required sites?					
		1 <sup>st</sup> month, 2 <sup>nd</sup> month, 3 <sup>rd</sup> month,	YES 🖂	NO   NO   NO		
	All DMRs reported "no flow".					
6.	Were all required DMR parameters reporte  Comments, including identity of monitoring		YES 🖂	№ □		
	All DMRs reported "no flow".					
7.	Were irregularities found in the DMR data?  Comments, including identity of monitoring		YES	NO 🛚		
	All DMRs reported "no flow".					
8. Based on your review, what further actions, if any, do you recommend?						
	No further actions are necessary at this tim	e.				
O:\007034.BAN\WATER QUALITY\DD2007.DOC						